




INSTITUTE OF HEALTH SCIENCES

(A Unit of Margdarsi)

Office: N-2/41, I.R.C Village, Nayapalli, Bhubaneswar – 751015, Ph.:0674-2553640, 2550054
Campus: Chandaka, Bhubaneswar, Khordha, Odisha, pin: 754005, E-mail: ihsbbsr@margdarsi.org, web: www.ihsindia.org



Director
Institute of Health Sciences
Bhubaneswar

Pioneer institution imparting Bachelor & Master's degree in Audiology and Speech Language Pathology and Physiotherapy
Modern Diagnostic & Complete Treatment center for Hearing Impairment, Multi Modal Therapy for CP, MR,
Autism, Learning Disability, Therapy for speech defects, Musculoskeletal Disorders and Neurological Problems.



INSTITUTE OF HEALTH SCIENCES

(A Unit of Margdarsi)

Office: N-2/41, I.R.C Village, Nayapalli, Bhubaneswar – 751015, Ph.:0674-2553640, 2550054

Campus: Chandaka, Bhubaneswar, Khordha, Odisha, pin: 754005, E-mail: ihsbbsr@margdarsi.org, web: www.ihsindia.org

C. C. Camera				
Dept.	Description	Status	Action	Remarks
10/5/21	Cam-2 Outside bullet Camera	blinking continuously	Problem identified. open the gun and the cable connecting the camera	Repaired & fixed. (15/5/21)
17/5/21	Academic Cam-2, 8.9 not working	Video loss & display	Problem rectified by going into Cable & Camera are working	Repaired & fixed. (17/5/21)
07/06/21	Academic Cam-2, 8.9 not working	The cable of the camera is not working	Cable of the camera is not working. Problem identified. Replaced the cable.	Repaired & fixed. (17/6/21)
05/11/21	Academic Cam-2, 8.9 not working	Verification of the cable of camera & cable connectivity	purchase order issued	
8/11/21	Academic Cam-2, 8.9 not working	Installation of camera & cable connectivity	inspection now in house. All & all work as per vendor	Status ok. (11/11/21)
09/03/22	Scholar for Academic Cam-2, 8.9 not working	Requirement of camera & cable connectivity	purchase order issued	Repaired & fixed. (15/3/22)

Electricals			
Date	Description	Status	Remarks
29/6/21	fan not working	repaired and fixed	
21/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (21/10/21)
30/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (30/10/21)
31/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (31/10/21)
31/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (31/10/21)
31/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (31/10/21)
31/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (31/10/21)
31/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (31/10/21)
31/10/2021	Academic Cam-2, 8.9 not working	Replaced 2 nos. 5amp switch & 1 nos. 5amp socket	Repaired & fixed. (31/10/21)

Water Purifier			
Dept.	Description	Status	Remarks
13/05/21	Aquaguard	checked and changed filter	Cartridge changed. (13/5/21)
10/6/21	Aquaguard	cartridge changed	Cartridge changed. (10/6/21)
8/10/22	Change Aquaguard	OK	Problem solved. (8/10/22)
20/05/22	Aquaguard	checked. The pipe is broken	Replaced & fixed. (20/5/22)

Plumbing			
Date	Description	Status	Remarks
02/04/2021	Wash room	OK	
2	Tape	Academic staff room	Academic staff room. (2/4/21)
3	Leakage	Public toilet	Public toilet. (3/4/21)
4	Water line	no issue	
5	Open Well	OK	
6	Pumps	OK	
7	Comedy panel	OK	
8	Overhead tank	no issue	
23/05/2021	Plumbing	no issue	
8/04/2022	Plumbing	no issue	

Director
Institute of Health Sciences
Bhubaneswar